

From: Fax Server +1 (732) 942-1114 To: Kevin Hesse (Business Fax)

Date: 4/13/00 Time: 8:31:04 PM

Page 1 of 1

MaxFlight
CORPORATIONMaxFlight Corporation
750 Airport Road
Lakewood, NJ 08701-5907 USA+1 (732) 942-9898
fax +1 (732) 942-1114
www.maxflight.com**SERVICE BULLETIN**

To: **Kevin Hesse (Business Fax)**
Fax: **17349968458**
Company: **Tri-Oxy Inc**
Subject: **MaxFlight Safety Service Bulletin 2000-05**
Sent: **4/13/00 at 6:30:00 PM**

From: **Rich Mascolo**
Fax: **+1 (732) 942-1114**
Voice: **+1 (732) 942-9898 235**
Pages: **1 (including cover)**

MESSAGE

Units Affected: All MaxFlight Simulators [VR2000, VR2002, VR2500 and MT3000]

Purpose: To ensure security of both Pitch and Roll Encoders

Action/Requirement: URGENT - SAFETY Bulletin

Instructions to comply with this SAFETY Bulletin:

- Locate the two set screws on the pitch encoder collar, remove and re-install using Blue Loc-Tite and ensure that the screws are tightened firmly.
- Locate the one set screw on the roll motor encoder shaft collar, remove and re-install using Blue Loc-Tite and ensure that the screw is tightened firmly.

We have made it a weekly requirement to inspect both encoders for security and set screws for tightness. Please add this requirement to your present weekly inspection.

*Completed 4/14/00**Kevin Hesse***IMPORTANT!**

Please CONFIRM RECEIPT of this Service Bulletin by faxing this cover page with your signature to MaxFlight Corporation at +1 (732) 942-1114 within 2 days.

URGENT

Signature (confirming receipt)